



JOHN DEERE OEM SALÉS DIVISION Moline, Illinois 61265


> OEM 81-1 18 February 1981

TO: SERVICE MANAGER
PURCHASING MANAGER

JOHN DEERE SERIES 300 OEM ENGINES

Because of today's rapidly changing nature of fuels and lubricants, the following changes have been approved and are now in effect:

- A. All 300 Series Engines
 - 1. Oil change interval has been changed from 200 hours to 100 hours
- B. 3164D 4219D Model Engines
 - 1. Crankcase oil fill capacity has been increased from 6 to 9 quarts with filter change
 - 2. To increase the crankcase capacity of 3164D 4219D engines from 6 9 quarts either remark the present AT21534 dipstick (see sketch) or install a new dipstick part number AR78192.



All customers should be informed of these changes and advised to implement them immediately.

| | | , | |
|--|--|---|--|
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |